Approved For Release 2000/04/\$\frac{1}{2000} PHOTOGRAPHIC EVALUATION REPORT

(Tracker Camera)

Copy No._

Mission No. <u>G 3065</u>	Evaluation Date 20 Apr 62 1	PER No	FE 19-62
Camera No18	Exposure Interval 32 sec	Scan Time	½ sec
Filter Red	Mission Duration 11 hrs 45 mins 25X1D	Total Foots	nge 1000
1. Film metering			
2. Format alignment	Good throughout mission		
3. Clock operation	Operational throughout mission		
Data chamber 4. (image quality)	Slightly overexposed, numbers blurred	<u></u>	
5. Banding	Very slight		
6. Apparent fog	Frames 176-179, 189		
7. Abrasions and scratches	Scratch on frames 78, 235		
8. Tearing (film)	None		
9. Density	Medium - 70%, heavy-30% (cloud shadow)		
10. Contrast	Medium - 70%, low - 30% (cloud shadow)		
11. Apparent resolution	Fair		
12. Apparent granularity	Medium		
13. Flare and light streaks	Flare on frames 372-400, 410		
Level bubble 14. operation			
15. Suitability for PI (film quality)	Fair due to 30 percent cloud coverage		: <u></u>

Remarks:

- Cverlap 60-70 percent, average 65 percent.
 Isolated and scattered examples of image motion along x axis throughout probably result of erratic scan.
- 3. Emulsion lifted on frames 111, 365.
 4. Foreign matter on frame 21.
- 5. Titling deposit on frame 159. 6. Last frame 410.

SPECIAL HANNLING